



930T

Digital LUX Meter

<b>Functions</b>	MAX / MIN, Backlight, Auto Power Off with Disable Feature, Data Hold
<b>Range</b>	0.1 ~ 200,000 lux 0.0 ~ 20,000 fc
<b>Accuracy</b>	±3% + 30 dgt
<b>Resolution</b>	0.1 lux or 0.1 fc
<b>Selection</b>	lux / fc
<b>Power</b>	1.5V AAA x 2 Batteries
<b>Dimension</b>	157 x 54 x 34mm (approx.)
<b>Weight</b>	170gms Including Battery (approx.)
<b>Accessories</b>	Carrying Case, Inst. Manual, 1.5V AAA x 2 Batteries (installed)



910

Infrared Thermometer

<b>IR Temperature</b>	
<b>Functions</b>	HOLD / MAX / MIN / MAX-MIN / AVG / APO
<b>Range</b>	-30°C ~ 550°C, -22°F ~ 1022°F
<b>Accuracy</b>	±(2°C / 4°F) for -30°C ~ 100°C, (-22°F ~ 212°F) ±(2% reading) for 101°C ~ 550°C (213°F ~ 1022°F)
<b>Resolution</b>	0.1°C, 0.1°F
<b>Emissivity (ε)</b>	0.1 ~ 1.0 (Adjustable)
<b>Air Temperature</b>	
<b>Range</b>	-20°C ~ 60°C, (-4°F ~ 140°F)
<b>Accuracy</b>	±0.5°C for 0°C ~ 45°C, ±1.0°C for -20°C ~ 0°C, 45°C ~ 60°C, ±1.0°F for 32°F ~ 113°F, ±2.0°F for -4°F ~ 32°F ~ 113°F ~ 140°F
<b>Resolution</b>	0.1°C, 0.1°F
<b>Power</b>	1.5V AAA x 2 Batteries
<b>Dimensions</b>	25 x 51 x 133mm (approx.)
<b>Weight</b>	125gms Including Battery (approx.)
<b>Accessories</b>	1.5V AAA Battery (installed) x 2 Wristlet x 1, Protection Cap x 1



961

Hygro Anemometer

<b>Wind Velocity</b>	
<b>Functions</b>	HOLD / MAX / MIN / MAX-MIN / AVG / APO
<b>Range</b>	0.4 ~ 20 m/s, 80 ~ 4000 ft/m
<b>Accuracy</b>	±0.2 m/s + 2% of reading, ±40 ft/m + 2% of reading
<b>Resolution</b>	0.1 m/s, 1 ft/m
<b>Relative Humidity</b>	
<b>Range</b>	0% ~ 100% RH
<b>Accuracy</b>	±2.5%, 10 ~ 90% RH [at 25°C (77°F)] ±5%, 0 ~ 10% RH, 90% ~ 100% RH
<b>Air Temperature</b>	
<b>Range</b>	-20°C ~ 60°C, -4°F ~ 140°F
<b>Accuracy</b>	±0.5°C for 0°C ~ 45°C, ±1.0°C for -20°C ~ 0°C, 45°C ~ 60°C, ±1.0°F for 32°F ~ 113°F, ±2.0°F for -4°F ~ 32°F ~ 113°F ~ 140°F
<b>Resolution</b>	0.1°C, 0.1°F
<b>Power</b>	1.5V AAA x 2 Batteries
<b>Dimensions</b>	25 x 51 x 133mm (approx.)
<b>Weight</b>	135gms Including Battery (approx.)
<b>Accessories</b>	1.5V AAA Battery (installed) x 2, Wristlet x 1, Protection Cap x 1



920

Thermo Hygrometer

<b>Humidity Measuring</b>	
<b>Functions</b>	HOLD / MAX / MIN / MAX-MIN / AVG / APO
<b>Range</b>	0% ~ 100% RH
<b>Accuracy</b>	±2.5% for 10% ~ 90% RH [at 23±5°C (73.4±9°F)] ±5% for 0 ~ 10% RH, 90 ~ 100% RH
<b>Temperature Measuring</b>	
<b>Range</b>	-20°C ~ 60°C (-4°F ~ 140°F)
<b>Accuracy</b>	±0.5°C for 0°C ~ 45°C, ±1.0°C for -20°C ~ 0°C, 45°C ~ 60°C, ±1.0°F for 32°F ~ 113°F, ±2.0°F for -4°F ~ 32°F, 113°F ~ 140°F
<b>Resolution</b>	0.1°C / °F
<b>Power</b>	1.5V AAA x 2 Batteries
<b>Dimensions</b>	25 x 51 x 133mm (approx.)
<b>Weight</b>	112gms Including Battery (approx.)
<b>Accessories</b>	1.5V AAA Battery (installed) x 2, Wristlet x 1, Protection Cap x 1